

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 18 November 2015 in accordance with regulation 10 of the Regulations, that Gear Engineering Limited, being a Class 1 and 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 29 March 2012 and 20 April 2012, the Contractor did respectively issue a Certificate of Fire Service Installation and Equipment which was false or misleading in a material particular, and such improper conduct or negligence will make his continued inclusion in the register of fire service installation contractors prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that name of Gear Engineering Limited be removed from the register of fire service installation contractors in Class 1 and 2 for a period of 14 days, which order was to take effect from 29 December 2015 to 11 January 2016.

KONG Ping-lam *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*