

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 12 May 2016 in accordance with regulation 10 of the Regulations, that F.S. Engineering Company Limited, being a Class 1 and 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on or about 3 December 2014, did issue a Certificate of Fire Service Installation and Equipment (no. 10386009651) stating that the fire service installation/equipment had complied with the requirements of the Fire Services Department whilst in fact a clear space of at least 0.5 m was not maintained below the level of the sprinkler deflectors throughout the room, and such improper conduct or negligence will make his continued inclusion in the register of fire service installation contractors prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that name of F.S. Engineering Company Limited be removed from the register of fire service installation contractors in Class 1 and 2 for a period of 7 days, which order was to take effect from 18 June 2016 to 24 June 2016.

KONG Ping-lam *Chairman, Registered Fire Service Installation
Contractors Disciplinary Board*