

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE INSTALLATION
CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 10 May 2017 in accordance with regulation 10 of the Regulations, that Far East Engineering Services Limited, being a Class 1 and 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment in that on 15 May 2016, during an after fire investigation at G/F-2/F, Tai Po Complex, 8 Heung Sze Wui Street, Tai Po, N.T., Far East Engineering Services Limited did NOT post a simple and standardized graphical notice detailing the shutdown of the fire service installation(FSI) at prominent locations during the FSI shutdown period according to para. 9(b) of The Fire Services Department Circular Letter No. 3/2008, and such improper conduct or negligence will make its continued inclusion in the register of fire service installation contractors prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(b) of the Regulations, the said Disciplinary Board ordered that Far East Engineering Services Limited be reprimanded, and the order will take effect on 21 June 2017.

NGAI Tak-yung *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*