

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE INSTALLATION
CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 10 May 2017 in accordance with regulation 10 of the Regulations, that Wylam's Services Limited, being a Class 1 and 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment in that on 27 May 2016, Wylam's Services Limited did issue a Certificate of Fire Services Installation and Equipment (No. 10135017586) without stating the defects of sprinkler system in the aforesaid certificate, namely, that in the system 6 numbers of alarm test valves to the sprinkler control valves were missing, and such improper conduct or negligence will make its continued inclusion in the register of fire service installation contractors prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(b) of the Regulations, the said Disciplinary Board ordered that Wylam's Services Limited be reprimanded, and the order will take effect on 22 June 2017.

NGAI Tak-yung *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*