

BUILDINGS ORDINANCE (Chapter 123)
(Section 35)

SERVICE OF ORDER

In accordance with the proviso to section 35 of the Buildings Ordinance, I append a copy of an order together with the available particulars of the persons to whom they are addressed as detailed below:—

**BUILDINGS ORDINANCE
(CHAPTER 123)
Order by the Building Authority under section 27A**

Order No. DH0046/NT/17/C

BD Reference No.: BD DH 37/15/NT

To: The owner(s) of Lot No. 98 in D.D. 387

Date : 24 October 2017

I am of the opinion that the earth-retaining structure (Feature No. 6SE-C/R101 as shown coloured pink on the attached plan) at Lung Yue Road, Tsing Lung Tau, New Territories on Lot No. 98 in D.D. 387 is liable to become so dangerous that it will collapse or be likely to collapse, either totally or partially, and thereby cause or be likely to cause a risk of injury to persons or damage to property.

2. In exercise of the powers vested in me under section 27A of the Buildings Ordinance, I hereby declare that such earth-retaining structure is liable to become dangerous and I HEREBY ORDER you as the owner of the land and structure, to carry out the following work :-

- a) appoint an authorized person and a registered geotechnical engineer within TWO months of the date of this Order to undertake the investigation required below;
- b) investigate, analyse, and report on the above earth-retaining structure, and submit remedial/preventive work proposals for approval by the Building Authority based on the findings of the investigation within SEVEN months of the date of this Order.

3. All work as stipulated above in this Order shall be carried out to such standard acceptable to the Building Authority and in compliance with regulations.



(HUI Ho-yin)
Senior Structural Engineer/Slope Safety(MW)
for Building Authority

Note

Subject to the findings of the investigation work as stipulated in this Order, you shall carry out any remedial/preventive work as required or approved by the Building Authority. Your attention is drawn to section 27A(2B) of the Buildings Ordinance that the Building Authority may by order in writing require the carrying out of such remedial/preventive work as appropriate within the specified time to make the land and structure safe. Under section 27A(2C), all work shall be carried out to such standard acceptable to the Building Authority and in compliance with regulations. Please also note that under section 27A(3) and (3A) of the Buildings Ordinance, the Building Authority may in certain circumstances carry out or cause to be carried out the work or investigation specified in the Order in which the cost thereof shall be recoverable from you or your successor in title as appropriate.

This issue : June 2012


The original copy of this order was posted upon a conspicuous part of the identified premises on its date of issue.

3 November 2017

LO Kai-cheung *Chief Building Surveyor/SS*
for *Building Authority*

Location: Lung Yue Road Tsing Lung Tau, New Territories
(新界青龍頭龍如路)

Lot No. 98 in D.D. 387 (丈量約份第 387 約地段第 98 號)



Location Plan(位置平面圖)

The plan is for indication only

此圖只作指示用途

Legends(圖例)

—— Feature Boundary (地物界線)
- - - Lot Boundary (地段界線)

█ 'P' Extent of DH Order (命令範圍)