

**G.N. 9735**

**ELECTRICITY ORDINANCE (Chapter 406)**

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ("the Ordinance"), I was satisfied on evidence and decided that Pricom Engineering Limited had failed to comply with Regulation 11(1) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that Pricom Engineering Limited, being a registered electrical contractor (Registration No.: 029211), between August and September 2016, was responsible for the electrical work at TBE Room 2, 1st Floor, Block 7, Double Cove Grandview, 8 Wu Kai Sha Road, New Territories but failed to provide protection by means of residual current device for a socket outlet circuit.

It is further notified that in accordance with section 36(1)(b)(i) of the Ordinance, I have reprimanded Pricom Engineering Limited.

22 December 2017

POON Kwok-ying for *Director of Electrical and  
Mechanical Services*