## BUILDINGS ORDINANCE (Chapter 123) (Section 35)

### SERVICE OF ORDER

In accordance with the proviso to section 35 of the Buildings Ordinance, I append a copy of an order together with the available particulars of the persons to whom they are addressed as detailed below:-

## BUILDINGS ORDINANCE (CHAPTER 123)

Order by the Building Authority under section 27A

Order No.

DH0028/NT/19/C

BD Reference No.: BD DH272/88/K(1)

To: The owner(s) of

Date: 11 June 2019

THE REMAINING PORTION OF LOT NO.3326 IN S.D.4

I am of the opinion that the natural, formed or man-made land (Feature No.11NW-A/C119 (Sub-division No.1) (Soil Slope Portion) as shown coloured red on the attached plan) at TSUEN WAN NEW TERRITORIES on THE REMAINING PORTION OF LOT NO.3326 IN S.D.4 is liable to become so dangerous that it will collapse or be likely to collapse, either totally or partially, and thereby cause risk of injury to persons or damage to property.

- In exercise of the powers vested in me under section 27A of the Buildings Ordinance, I hereby declare that such natural, formed or man-made land is liable to become dangerous and I HEREBY ORDER you as the owner of the land to carry out the following work:
  - appoint an authorized person and a registered geotechnical engineer within TWO months of the date of this Order to undertake the investigation required below;
  - investigate, analyse, and report on the above natural, formed or man-made land and submit remedial/preventive work proposals for approval by the Building Authority based on the findings of the investigation within SEVEN months of the date of this Order.
- 3. All work as stipulated above in this Order shall be carried out to such standard acceptable to the Building Authority and in compliance with regulations

CHOW Hing)

Senior Structural Engineer/Slope Safety for Building Authority

#### Note

Subject to the findings of the investigation work as stipulated in this Order, you shall carry out any remedial/preventive work as required or approved by the Building Authority. Your attention is drawn to section 27A(2B) of the Buildings Ordinance that the Building Authority may by order in writing require the carrying out of such remedial/preventive work as appropriate within the specified time to make the land and structure safe. Under section 27A(2C), all work shall be carried cut to such standard acceptable to the Building Authority and in compliance with regulations. Please also note that under section 27A(3) and (3A) of the Buildings Ordinance, the Building Authority may in certain circumstances carry out or cause to be carried out the work or investigation specified in the Order in which the cost thereof shall be recoverable from you or your successor in title as appropriate.

The original copy of this order was posted upon a conspicuous part of the identified premises on its date of issue.

21 June 2019

CHU Wai-yiu, Dick Chief Building Surveyor/SS for Building Authority

# **Location: TSUEN WAN NEW TERRITORIES** 置:新界荃灣 Lot Nos.: THE REMAINING PORTION OF LOT NO.3326 IN S.D. 4 地段編號: 測量約份第4約地段第3326號餘段 As shown coloured red 圖示紅色部分 Feature No. 11NW-A/C119 (SD1)(Soil Slope Portion) 地物編號 11NW-A/C119 (SD1)(泥土斜坡部分) A-TKT As referred to Order No.: DH0028/NT/19/C TWKT/KT/29/2013 關於命令編號: DH0028/NT/19/C 號 3326 S.E 3326 3326 S.F Roac S.N SD4SHT6 3326 + 20.6 S.J ss. 3326 S.G ss.1 S.J RP 3326 S.G 3326 S.I SS.2 5 3326 S.G RP Location Plan(位置平面圖) 此圖只作指示用途 The plan is for indication only Legends(圖例) Feature Boundary (地物界線) Extend of DH Order (命令範圍)

Lot Boundary (地段界線)