

**G.N. 5607**

**ELECTRICITY ORDINANCE (Chapter 406)**

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ("the Ordinance"), I was satisfied on evidence and decided that Joint Effort Engineering (Asia) Limited had failed to comply with section 34(6) of the Ordinance in that Joint Effort Engineering (Asia) Limited, being a registered electrical contractor (Registration No. : 009359), on 4 March 2017, at the Meter Room at Corridor near Room 214, 2nd Floor, Fook Wo House, Tai Wo Estate, Tai Po, New Territories, failed to effectively supervise a registered electrical worker employed by him, resulting in the occurrence of an incident of cable damage and electricity supply interruption.

It is further notified that in accordance with section 36(1)(b) of the Ordinance, I have reprimanded and fined Joint Effort Engineering (Asia) Limited \$5,000.

*6 September 2019*

LAI Hon-chung for *Director of Electrical and Mechanical Services*