

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 12 May 2016 in accordance with regulation 10 of the Regulations, that Century Fire Service Engineering Company Limited, being a Class 1 and 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on or about 12 July 2012, did issue a Certificate of Fire Service Installation and Equipment (no. A6123407) stating that the fire hose reel systems conformed with the requirements of the Fire Services Department whilst in fact the fire hose reel systems were not connected to a water supply, and such improper conduct or negligence will make his continued inclusion in the register of fire service installation contractors prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that name of Century Fire Service Engineering Company Limited be removed from the register of fire service installation contractors in Class 1 and 2 for a period of 14 days, which order was to take effect from 27 June 2016 to 10 July 2016.

KONG Ping-lam *Chairman, Registered Fire Service Installation
Contractors Disciplinary Board*