ELECTRICITY ORDINANCE (Chapter 406)

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ('the Ordinance'), I was satisfied on evidence and decided that Mr. LEUNG Chik Kuen had failed to comply with Regulation 19(1) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that Mr. LEUNG Chik Kuen, being a registered electrical worker (Registration No. W060588), between 1 May 2015 and 13 November 2015, carried out lighting replacement work at Lobbies of Royal Ascot, Fo Tan, New Territories but failed to certify the fixed electrical installation before it was energised for use to confirm that the requirements of the Ordinance had been met.

It is further notified that in accordance with section 36(1)(b)(i) of the Ordinance, I have reprimanded Mr. LEUNG Chik Kuen.

9 September 2016

LAI Hon-chung for Director of Electrical and Mechanical Services