

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 8 December 2016 in accordance with regulation 10 of the Regulations, that Chavez Engineering Limited, being a Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 4 February 2015, did issue a Certificate of Fire Services Installation and Equipment (No. 20550150202) stating that the Fire Hydrant/Hose Reel system complies with FSD requirements when in fact the capacity of the water tank used was only 2000L falling short of the required capacity of 9000L, and such improper conduct or negligence will make his continued inclusion in the register of fire service installation contractors prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that name of Chavez Engineering Limited be removed from the register of fire service installation contractors in Class 2 for a period of 14 days, which order was to take effect from 17 January 2017 to 30 January 2017.

NGAI Tak-yung *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*