

G.N. 1209

CIVIL AIRCRAFT ACCIDENT—INSPECTOR'S INVESTIGATION

Notice is hereby given that an Inspector's Investigation is being conducted into the circumstances and causes of the accident which occurred on 26 February 2017 whereby a Cessna Model 152 aircraft with registration B-HHN, registered in the name of and operated by Hong Kong Aviation Club Limited, came into contact with and rested in trees when the pilot was executing a forced landing due to a reported engine problem, at the Garden Farm Golf Centre in Ma On Shan. The left wing of the aircraft was broken; the two persons on board were not injured in the accident.

Any person who wishes to make representation as to the circumstances or causes of the accident should do so by letter, facsimile, telephone, or email to the Chief Inspector of Accidents (address: Civil Aviation Department Headquarters, 1 Tung Fai Road, Hong Kong International Airport, Lantau, Hong Kong; Telephone: 2910 6145; Facsimile: 2326 3654; or Email: ctng@cad.gov.hk) within 14 days of this notice.

10 March 2017

Simon LI Chief Inspector of Accidents