

**G.N. 1245**

**ELECTRICITY ORDINANCE (Chapter 406)**

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ('the Ordinance'), I am satisfied on evidence and have decided that Mr. CHOW Tung Hoi had failed to comply with Regulation 4(2) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that Mr. CHOW Tung Hoi, being a registered electrical worker (Registration No. W013662), on or about 30 August 2014, while carrying out electrical work in a premises at Flat C, 35th Floor, Block 5, Lynwood Court, Kingswood Villas, Tin Shui Wai, New Territories, did not provide protection by means of residual current device for socket outlet circuits.

It is further notified that in accordance with section 36(1)(b)(i) of the Ordinance, I have reprimanded Mr. CHOW Tung Hoi.

*10 March 2017*

LAI Hon-chung for *Director of Electrical and Mechanical Services*