

**G.N. 4102**

**ELECTRICITY ORDINANCE (Chapter 406)**

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ('the Ordinance'), I was satisfied on evidence and decided that Mr. TONG Yuk Chiu had failed to comply with regulation 4(7) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that Mr. TONG Yuk Chiu, being a registered electrical worker (Registration No. W033887), on 16 September 2015, at Shop 201, 2nd Floor, K11, 18 Hanoi Road, Tsim Sha Tsui, Kowloon, failed to ensure that safety precautions had been taken to prevent danger arising from electrical wiring work done by him since he resumed electricity supply to a distribution board without having covered up the live parts of the distribution board, causing electric shock and injury to himself.

It is further notified that in accordance with section 36(1)(b) of the Ordinance, I have reprimanded and fined Mr. TONG Yuk Chiu \$1,000.

22 July 2016

SIT Wing Hang for *Director of Electrical and Mechanical Services*