

G.N. 2819

ELECTRICITY ORDINANCE (Chapter 406)

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ('the Ordinance'), I was satisfied on evidence and decided that Mr. Chung Chun-yu had failed to comply with Regulation 4(2) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that Mr. Chung Chun-yu, being a registered electrical worker (Registration No.: W078928), on or about 28 December 2016, at Shops 31–33, L2, Sun Tuen Mun Shopping Centre, 55–65 Lung Mun Road, Tuen Mun, failed to install main switch properly for single phase installation.

It is further notified that in accordance with section 36(1)(b)(i) of the Ordinance, I have reprimanded Mr. Chung Chun-yu.

26 April 2019

VY Ek-chin for *Director of Electrical and Mechanical Services*